

Vzory a rozměry děrování



Typ	41/21/1,5	41/21/2,0	41/31/2,0	41/41/2,0	41/41/2,5	41/45/2,5	41/52/2,5	41/62/2,5	41-75/65/3,0	41-75/75/3,0	41/21/2,0 D	41/41/2,0 D	41/41/2,5 D	41/45/2,5 D	41/52/2,5 D	41/62/2,5 D	41-75/65/3,0 D	41-75/75/3,0 D
B [mm]	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41
H [mm]	21	21	31	41	41	45	52	62	65	75	41	82	82	90	104	124	130	150
t [mm]	1,5	2	2	2	2,5	2,5	2,5	2,5	3	3	2	2	2	2,5	2,5	2,5	3	3
e [mm]	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22
Vzor děrování											viz. jednoduché lišty							
b [mm]	12,5	13	13	13	13	13	13	13	13	13								
l [mm]	36,5	40	40	40	40	40	40	40	40	40								
d [mm]	-	-	-	-	-	-	-	-	17	17								

Typ	27/15/1,25	27/25/1,25	27/37/1,25
B [mm]	27	27	27
H [mm]	15	25	37
t [mm]	1,25	1,25	1,25
e [mm]	16	16	16
Vzor děrování			
b [mm]	8,5		
l [mm]	18,5		
d [mm]	10,5		